

ΕN

RF06730

Cable winder support






ΕN

RF06730

Cable winder support






Fig.1 Fig.2

It is necessary to hold the rod (B) and unfasten the knob (A). Unfasten the 2 screws (C) and free the broken cable winder support (D).

Assemble now the new spare-part:

Position the cable winder support (D) on the lamp base (E), ensuring that the holes present on the winder support (D) correspond with the holes present on the lamp base (E).

Tighten slightly the knob (A) without fastening it.

WARNING! When installing and whenever acting on the appliance, ensure that the power supply has been switched off. For the installation of the spare-part, it is necessary to consult a qualified electrician.

ΕN

RF06730

Cable winder support




Fig.3

Adjust the height of the rod (B) and then fasten the knob (A). Wrap the excess cable around the cable winding support (H).