

RF01089

4mt steel wire Ø1,2 with 19 winded wires



WARNING! When installing and whenever acting on the appliance, ensure that the power supply has been switched off.
For the installation of the spare-part, it is necessary to consult a qualified electrician.

RF01089

4mt steel wire Ø1,2 with 19 winded wires



Fig.1



Fig.2

Fig. 1: Using a flat screwdriver, unscrew the steel cable fixing screw (A)

Fig. 2: Holding the product structure still, pull out the steel cable and remove it. Perform the reverse procedure, installing the new steel cable and securing it securely with the white screw.

WARNING! When installing and whenever acting on the appliance, ensure that the power supply has been switched off.
For the installation of the spare-part, it is necessary to consult a qualified electrician.